

CONTOUR

Storyteller Version 3.0.8

Release Notes

May 9, 2011

Supported Platform(s):

- Intel based Macs with OSX 10.5 or later
- PCs w/Win XP (SP2), Vista or Win7


Storyteller 3.0.8 includes the following changes:

- Updated Configuration dialog
- Auto power shutdown setting for ContourGPS
- GPS Hz record rate setting for ContourGPS
- Send support information
- Feature reporting

Feature details

Updated Configuration Dialog

The new configuration dialog streamlines the act of changing settings on a camera. All the current functions are there in a newly laid out and reorganized view.



Auto power shutdown setting for ContourGPS

A new control for the ContourGPS is to control how long the camera will stay on before shutting down due to inactivity. This can be found in the camera tab of the configuration dialog.

GPS Hz record rate setting for ContourGPS

The GPS module of the ContourGPS offers guaranteed performance at both 1Hz and 2Hz(once or twice a second). The record rate can now be configured within the GPS section of the dialog. Although the module is capable of a 4Hz record rate, performance is not guaranteed at this level resulting in incorrect or missing GPS data. If you still wish to use the 4Hz setting, you can only do so by directly editing the FW_RTC file on the camera's SD card.

Send Support Information

At times, people using Storyteller may run into problems with the software. To assist Contour in troubleshooting bugs and other issues, there is now the ability for people to send troubleshooting details to Contour Support from within the application. To send support information to Contour, application logging will need to be enabled. Within the System Preferences dialog, select the 'Turn on application logging' checkbox. Retry the action which caused a problem, and then access the Send Support Info dialog from within the Help menu.

Feature Reporting

To provide better software in the future, Contour has added feature use reporting to the application. Anonymous data is sent to Contour showing the frequency with which features are used within Storyteller. This data will be used for feature planning. To disable this reporting, access System Preferences dialog.

Fixed Issues:

- Missing play/pause controls when in full screen
- Map Window Is Hidden When Info Window is Shown
- Full screen window blank when movie paused
- Events not deleting fully
- Default library location unable to be created
- Uploads with non Latin characters fail
- GPS speed now shown in tenths of a mile/kilometer
- Storyteller window isn't small enough for netbooks
- Storyteller may crash when switching to full screen on XP or Vista